

**Brookville Mining Equipment Corporation**  
**Product Information Bulletin 53 (02-16-01)**  
**Brookville Model 1260B-Xlow**  
**Stop Switch Elimination Procedure**

**Purpose:**

On Brookville Model 1260B-Xlow units, the stop switch in both the front and rear gauge panels is non-operational.

**Action:**

We are recommending that the stop switch be removed, and plugged to avoid any confusion, since this switch is designed to be non-operational in this unit. A free modification kit (12-0949) is available from Brookville Mining Equipment Corporation, which contains a plug for the switch, modification instructions, and the appropriate changes for the operation/parts manual noting this change.

**Serial Numbers Affected:**

8310, 8313, 8355, 8361, 8362, 8363, 8364, 8399, 83100, 8437, 8438, 8440, 8441

**Verification:**

Brookville Mining Equipment Corporation Service Manager will contact each mine with the above units, and ship the modification kit to each mine. After receiving and installing the kit, the mines are asked to return the stop switch modification form.

# **Stop Switch Modification Verification Form**

Please complete and fax back this modification form after the stop switch modification has been done.

Person Completing Modification Form:

\_\_\_\_\_  
Printed Name

\_\_\_\_\_  
Signature

Title:

Name of Company:

Address:

Phone:

( ) Our company has made the stop switch modification per kit 12-0949

Machine Serial Number:

Please Fax Back: Attention Harry Reitz  
Fax Number: 814-849-2010  
Email: [hreitz@brookvillecorp.com](mailto:hreitz@brookvillecorp.com)